



# PUMPDOWNTIME TO $1 \times 10^{-9}$ TORR (50 Bolts in Chamber)

- Vented Bolt, using 5% of a 10 l/s pump
- Non Vented Bolt, using 5% of a 10 l/s pump



# PUMPDOWNTIME TO $1 \times 10^{-9}$ TORR (50 Bolts in Chamber)



# PUMPDOWN TIME TO $1 \times 10^{-9}$ TORR

## (50 Screws/Bolts in Chamber)

